

BACKGROUND

What is the Problem?

- Legacy diver-below buoys are no longer manufactured
- Readily available products are insufficient
- Current buoy is experiencing corrosion and environmental degradation

What is a Diver Below Buoy?

- Location/Perimeter Marker
- Resting Platform
- Safety Mechanism

Mission Statement

Design, manufacture, and install six durable diver-below-buoys to support 3 to 4 divers, provide stable flotation, storage, and durability for long-term reliability and cost efficiency.

FINAL DESIGN



- Red marine grade, vacuum molded HDPE shell
- Marine grade closed cell foam core
- 3 feet in diameter
- Supports 4-5 divers
- Resistant to galvanic corrosion, UV degradation, rips, tears, and punctures
- Product life of 7-10 years

Cost Analysis

Annual Estimated Maintenance Cost

Currently in use buoys	\$950- \$1,200.00
General market buoys	\$2,000-\$2,500
Our Buoys	\$0.00

Per Unit Cost


Currently in use buoys	\$495.00
Our Buoys	~\$300.00

ME2.02 – Logan Mallow, Claudia Quilter, Andres Herrera, Ryan Beakley

Design and Fabrication of Diver Below Buoys

VACUUM FORMING MACHINE DEVELOPMENT

Heating Array Systems Test



TEST 1
Uneven heating of plastic sheet

TEST 2
Added aluminum hotplate to heating elements

Plastic still heated unevenly


TEST 3
New larger heating element array was wired and installed

Proper heating
Improper vacuum seal

TEST 4
Vacuum leaks isolated and sealed

Held under heat too long


Thermal Imaging




Thermal gradient on the aluminum sheet before and after the heating system upgrades

FABRICATION

I. Forming Process Machine



A top and bottom buck is machined out of MDF and is used to form all six buoys



Marine grade HDPE is heated to its glass transition temperature (130°C-160°C)



Heated plastic is lowered over the mold on a vacuum table



The HDPE is then cut and processed

II. Foam Filling



Each half of the buoy is filled with a two-part expanding foam

III. Plastic Welding



The two halves are then plastic welded together to create the final buoy

DEVELOPMENT PROCESS

I. Identifying Customer Needs

Market Research

- Similar market products
- Material research papers
- Diver-below buoy patents
- Ergonomics
- Stability of system
- Set-up process

Interviews

Self Tested



II. Established Design Specifications

Longevity: 3–5-year service life in outdoor aquatic environments

Buoyancy: Comparable stability and floatation performance to the buoys currently in use


Durability: Resistant to marine wear-and-tear and UV degradation

Diver Stability: Supports 3-4 divers


Storage: Securely holds extra diving weights for diving instructors to quickly access

Low Maintenance: Maintenance cycles and labor requirements are equal to or lower than the in-use buoy

III/IV. Concept Generation & Selection




Selection Criteria	Material Form	Material Form	Material Form	Material Form	Material Form	Material Form	Material Form
Weight	G	1	2	3	4	5	6
Strength	G	1	2	3	4	5	6
Cost	G	1	2	3	4	5	6
Manufacturability	G	1	2	3	4	5	6
Environmental	G	1	2	3	4	5	6
Stability	G	1	2	3	4	5	6
Storage	G	1	2	3	4	5	6
Weight	G	1	2	3	4	5	6
Strength	G	1	2	3	4	5	6
Cost	G	1	2	3	4	5	6
Manufacturability	G	1	2	3	4	5	6
Environmental	G	1	2	3	4	5	6
Stability	G	1	2	3	4	5	6
Storage	G	1	2	3	4	5	6



V. Scaled Fabrication Testing

Scaled Test



FMEA

Design Req or Process Function Requirements	Potential Failure Mode	Potential Effects of Failure	Severity	Potential Cause(s) / Mechanism(s) of Failure	Occurrence	Detection	Current Design or Process Controls	RPN
Mid-seam weld (diver halves)	Seam weld failure / internal leak	Structural failure; loss of buoyancy	10	Filler contamination; poor bead control; poor weld control	4	Visual inspection, and scaled proof-test weld joint before use	Visual inspection, and scaled proof-test weld joint before use	160
Handles for diver support	Handle tear-out	Injury risk; change to buoy	8	Insufficient foam filling (air gaps)	4	Handles are fitted separately from the core and inspected before the 2nd half is joined; also a weight increase is incorporated	Handles are fitted separately from the core and inspected before the 2nd half is joined; also a weight increase is incorporated	128
Structural support (foam core)	Foam overexpansion / poor closed-cell	Increased weight / poor closed-cell	7	poor sealing; open-cell foam used	1	Verify the 2-part expansion before use	Verify the 2-part expansion before use	7
Vacuum formed shell thickness	Excessive draw (warping / thin corners)	Local dents, crack initiation	6	Deep draws; sharp radii; poor heating profile	3	Scaling of 2:1 for vacuum forming and measuring thickness with calipers before use	Scaling of 2:1 for vacuum forming and measuring thickness with calipers before use	36
Foam expansion (during fill)	Over expansion / uneven fill	Warping shell; local air spaces	5	No vent/overflow; excessive foam; high ambient temp	3	Scaled foam expansion test before use	Scaled foam expansion test before use	30
Anchor to platform	Anchor to platform failure under load	Buoy loss; hazard to other craft	5	Cyclic fatigue; stress concentration	2	proof-load pull to 2x design load (20-80 lb)	proof-load pull to 2x design load (20-80 lb)	20

Acknowledgements

Dr. Austin Talley
Assistant Professor, Ingram School of Engineering

Aaron Wallendorf
Lake Manager, Spring Lake Operations



THE MEADOWS CENTER
FOR WATER AND THE ENVIRONMENT
TEXAS STATE UNIVERSITY

Dr. Mohamed Abdelkareem
Assistant Professor, Ingram School of Engineering

Michael Flores
Spring Lake Dive Coordinator

